FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	entrological de la destara de la proposición de la destaración de la destaración de la destaración de la desta
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED.
and the second of the second o	en e
vice at the state of the second section is the second seco	na servicina de la companya del companya de la companya del companya de la compan
en e	
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE

REMARKS _

Nº 8190

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF HOLDER	BAUM FEE OF \$ 5.0
$\frac{1}{2} \left(\frac{1}{2} \right) \right) \right) \right)}{1} \right) \right) \right)}{1} \right)} \right)} \right)} \right)} \right)} \right)} \right)} \right)}}} \right)}}}}}}}}$	
FOR WHICH PERMISSION IS GRANTED	
TO TAP SAN ITARY (REPAIR) SE	WER ON THE WEST
05 735-3 PN.E AVE. TY	PE OF STREET BLACK TOP
THE PREMISES BEING LOT NO.	HOUSE NO. 735-38

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HOLDERBAUM

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.