

N^o


9680

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNEDDATE INSPECTED 4-4-85IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 224DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHSIZE OF PIPE USED 6"WAS LATERAL AT CURB? —WAS ATTACHED TO MAIN —

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N 4



SIGNED

Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair in front of F.W. Arnold building. Clean out put in.

Repair
N^o 9680

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *June 3*

RECEIVED OF

J. Haldeman

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED

Haldeman Sewer

TO TAP

Sanitary

SEWER ON THE

with

OF

Lincoln St. East

AVE.

ST. TYPE OF STREET

asphalt

THE PREMISES BEING LOT NO.

132

, HOUSE NO.

224

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Haldeman
Repair

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**