

Nº 10151

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED 11-21-91

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM 63'

HOUSE NO. 332

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR A. J. Diana & Son's

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



The Wastewater Treatment Department is liable for the contractor not installing back-flow preventer or shut off valve sewer lateral. The City Inspector suggests that this be done.

Ronald L. Halter 1-8-  
Ronald L. Halter  
Manager/Supt., WWTD

SIGNED Bill Pagnus  
Inspector for City

FILED AT ENGINEER'S OFFICE \_\_\_\_\_

REMARKS \_\_\_\_\_

*itap*  
Nº 10151

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS  
**PERMIT TO TAP SEWER**

MASSILLON, OHIO, *Nov 4,*

RECEIVED OF *AT Home Inc*

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *to Home*

TO TAP *Sanitary*

SEWER ON THE *Plumbing*

OF *200th St*

AVE.  
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *14727*

HOUSE NO. *332*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *AT Home Inc*

*Masonic Assoc  
of Massillon*

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**