Nº 10757

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-12-98	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO3//	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT
WAS LATERAL AT CURB? 45 9	CURB LINE AND DEPTH
WAS ATTACHED TO MAIN 155	NAME OF CONTRACTOR 25 La Barrier
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	•
Short 2. Pinatani Manaratani and	CURB
	39'6'DIED 6"FAIL
	145° 5'4"= 00 NA
SIGNED Bill Company	FILED AT ENGINEER'S OFFICE
, ·	

Nº 10757

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/12
Halderbeirned FEE OF SE
EWER ON THE
rype of street
, HOUSE NO
NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
and the second

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.