Nº 11240

REMARKS -

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-11-6/ HOUSE NO. 2490	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
, , , , ,	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED 6	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 45	NAME OF CONTRACTOR Bonking in Egg.
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR To on truy in try.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
x1.)	136' 8'DFF S
747	9'
'	L 45° 14 DARD
SIGNED Bill and	FILED AT ENGINEER'S OFFICE
Inspector for City	

Nº 11240

OFFICE OF THE DIRECTOR OF PUBLIC SERVICI PERMIT TO TAP SEWER

d.	MASSILLON, OHIO,
//	
RECEIVED OF TOUCH A SECOND	4 CACAVATAG FEE OF \$ 50
FOR WHICH PERMISSION IS GRANTED	Elevent Homes
REPAIR TO TAP	EWER ON THE
CUTOFF	YPE OF STREET And And A
'	59 , HOUSE NO. 2490
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO.	19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	a
NAME OF CONTRACTOR	ecu ck-121566

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.