N^{0} 11399

REMARKS _____

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	11/15/01	_ IF SO, HOW AND LOCATION FROM	33'		
HOUSE NO	354	FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
SIZE OF PIPE USED	6"				
WAS LATERAL AT CURB?	yes			white was a second seco	
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR	Tissot		
SHOW BY DIAGRAM RELATION	OF LATERAL TO WALL OF	BUILDING SERVED.			
			354 Kaylynn	12'- -17' -22' -22. -39'	7
SIGNED W/K	1/4	FILED AT ENGINEER			——•
SIGNED	Unspector for City	TILED AT ENGINEER	TO OFFICE	4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 -	***************************************

Nº 11399

OFFICE OF THE DIRECTOR OF PUBLIC SERVICI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	11 - 15	, 20
RECEIVED OF		FEE OF \$ _	5
FOR WHICH PERMISSION IS GRANTED	T1550+		
REPAIR TO TAP	SEWER ON THE	Enst	
OF Kaylyna 5 E			
THE PREMISES BEING LOT NO. 15218		•	354
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E NO 19 1971 DULY PASSED BY THE	CITY COUNCIL AND RULE	S OF THE
DEPARTMENT OF PUBLIC SERVICE.	1		,5 51 1712
NAME OF CONTRACTOR	e +		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.