Nº 11593

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8/5/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO330	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTORTissot
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF B	UILDING SERVED. 330 Koylynn SE
	182 177
Not to scole	22°-(-10'dp
	62-
11	₫ Topped into MH
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
, ,	
DEMARKS	

N° 11593

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	07/31/020_
RECEIVED OF	+ Excavating	FEE OF \$1 - 24 5
OR WHICH PERMISSION IS GRANTED	Tissot	the state of the s
REPAIR O TAP FR SCALORY CUTOFF	SEWER ON THE	east .
OF KaylyAA St SE	AVE, ST. TYPE OF STREET	asphalt
THE PREMISES BEING LOT NO	22.19 , HOUSE NO. 2	33()
VORK TO BE DONE IN ACCORDANCE WITH ORDINAN DEPARTMENT OF PUBLIC SERVICE.	ICE NO. 19.1971 DULY PASSED BY THE CI	TY COUNCIL, AND RULES OF THE
IAME OF CONTRACTOR	+	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.