Nº 11607

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8/21/02	IF SO, HOW AND LOCATION FROM 125'	
HOUSE NO. 643	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB? Yes	CURB LINE AND DEPTH	AMANANA PROFESSION ASSESSMENT OF THE SECOND AS
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Glick
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	. OF BUILDING SERVED.	643 Washington St NW
Not to scole		7.25° dp
		3: 45'
-,		
SIGNED BILL Pappa 5 Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 11607

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSIL	LON, OHIO,	08/24	102,20_
RECEIVED OF			FEE OF \$	
FOR WHICH PERMISSION IS GRANTED	Keun	6/ick		<u> Kirani</u>
REPAIR TO TAP TO Sundate!	SEWER ON THE	_ , 	West	
OF WALL FIN	AVE, LEPTYPE OF STRE	ET	acpholt	
THE PREMISES BEING LOT NO.				.43
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC DEPARTMENT OF PUBLIC SERVICE.	E NO. 19.1971 DULY	PASSED BY THE CI	TY COUNCIL, AND R	ULES OF THE
NAME OF CONTRACTOR	Click		<u> </u>	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.