Nº 11661

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED12/10/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM ?			
HOUSE NO609				
SIZE OF PIPE USED6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB? Yes				
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR Plgs Exc.			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BL	JILDING SERVED. SOS CRI CT NE 2' 01 6" replace w/ 6" pvc - 5"dp lateral was apparently broken by water line.			
SIGNED John Inspector for City	FILED AT ENGINEER'S OFFICE			
REMARKS				

Nº 11661

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	10	MASSILLON, OH	10,	12 /200
RECEIVED OF	1/10	(Alain)	TZ FEE	E OF \$
FOR WHICH PERMISSION IS GÂAN	ΓED		. 0	Į.
REPAIR J	ed C17	SEWER ON THE		S
CUTOFF OF	astasas	AVE. ST. TYPE OF STREET	10: 1	1 * 1 -
HE PREMISES BEING LOT NO	<u>Ú</u> _	タフス	OUSE NO.	609
	•			/ .
VORK TO BE DONE IN ACCORDANG	E WITH ORDINANCE	NO. 19.1971 DULY PASSED	BY THE CITY COUNCIL,	AND RULES OF THE
PEPARTMENT OF PUBLIC SERVICE	10	1		j.
IAME OF CONTRACTOR	- MA	CNUMBA	19/	
			~ // -	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.