

## CITY OF MASSILLON, OHIO

**151 LINCOLN WAY EAST MUNICIPAL GOVERNMENT ANNEX CITY ADMINISTRATION BUILDING MASSILLON, OHIO 44646** PHONE 330-830-1722 FAX 330-830-1786

PERMIT DA	ATE:
-----------	------

12/2/2005

PERMIT NO.

3558

## PERMIT TO TAP SANITARY SEWER

of start of work (330) 830-1722. All permits issued under this ordinance are void after 120 days from date of issuance.				
RECEIVED OF: PERMIT TYPE: V NEW REPAIR CUTOFF				
CONTRACTOR INFORMATION SITE INFORMATION				
CONTRACTOR:	A J DIANA & SONS	OWNER'S NAME:	BRIARWOOD BUILDERS	
CONTACT:		STREET NUMBER:	1391	
ADDRESS:		STREET NAME:	WOODFORES ST N	
CITY:		CITY LOT NUMBER	16671	
STATE:	management produced to the state of the stat	PURPOSE OF CUT:	SANITARY	
ZIP:		ZONING CLASS:		
PHONE:	(330) 832-5904	STREET SIDE:	WEST	
FAX:		PHONE OTHER:	(330) 830-0844	
SURETY:	and the second section of the second second section is a second second second second second section of the second	NOTE: This permit covers work walls of the building is subject t	outside of the building ONLY. Any work inside the Massillon Board of Health Regulations.	
SANITARY SEW	ER CONNECTION:		WING #:	
USAGE:   RESIDE	NTIAL () COMMERCIAL () INDUSTRIAL	1391 Woodfores	1/2000	
DATE INSPECTED	1/30/2006	1391 Moddares	#5555	
located on the	/EST side of	-8'-1  6'dp		
WOODFOREST ST	T NW between	-6,		
WOODSTONE AVI	E SE and	45. 22.		
BRIGHTLEAF AVE	A company of the contract of t		<b>—</b>	
Direction from downstream Manhole: SOUTH 45' 6'				
Distance from downstream Manhole: 181'		16'dp	45°	
Connection Lengt	h: 38.00 (FEET)	ext -		
Connection Depth	: 16 (FEET)	curb		
Size of Sewer Pipe	e: 6 (INCH	ES) INSPECTION RI	181'	
Pipe Material:	PVC	INSPECTION KI	EQUEST.	
INSPECTORS NAM	ME: JEFF KING	SANITARY SEWI	ER PERMIT FEE: \$100.00	
COMMENTS:			The state of the s	
		•	TOTAL COST: \$100.00	
TWO WORKING DAYS BEFORE YOU DIG  Object Heliting Destruction Consider Consider Services  AUTHORIZED BY: DIRECTOR OF PUBLIC SAFETY AND SERVICE				
Ohio Utilities Protection Service Call 1-800-362-2764 Toll Free ISSUED BY: LINDA MIKUTEL		The second secon		
Non-Members must be called directly.			The second secon	