| Mew connection FOLLOWING DATA TO BE ANSWERED BY INSPECTOR                                     |          |
|---|----------|
| FOLLOWING DATA TO BE ANSWERED BY INSPECTOR $ ho_{f N}^{o}$ AND SIGNED WHEN RETURNED           |          |
| DATE INSPECTED 6-1-42 If so how and location from FIRST MANHOLE DOWN STREAM                   |          |
| House No. 738  Distance from first manhole Down Stream to ditch at ZZ3' 6'-6" At Ca           | U I      |
| WAS LATERAL AT CURB? U.S. NAME OF CONTRACTOR Acres Mrlsm                                      |          |
| Show by diagram relation of lateral to wall of building served.  Length of lateral 4/th. from | V        |
| curb to bouse.  6-6" Deep at Curb   |          |
| 6-0" " " House N. Curb  | カナ       |
| 223'  |          |
| SIGNED FILED AT ENGINEER'S OFFICE JUNE 2 1942 G   | <u>ڪ</u> |
| REMARKS: C/QY 501/  |          |

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

|     | The second process was as the second | Agrogsen brace  |
|-----|---|---|
|     | MASSILLON, OHIO,  | 10 10 200 300 300 10 10 10 10 10 10 10 10 10 10 10 10 1 |
| the | RECEIVED OF   | FEE OF SZ   |
|     | FOR WHICH PERMISSION IS GRANTED   | or conce <b>d</b> Analy                                 |
| T   | O TAP SEWER. ON THE   | 20/02/20/20 12 12 12 12 12 12 12 12 12 12 12 12 12      |
| •   | OF TOTAL (MANAGE, TYPE OF STREE   |   |
| т   | THE PREMISES BEING LOT NO. $\frac{7996}{}$ House No   | . 738   |
|     | Work to be done in accordance with Ordinance No. 2323, duly pa  | SSED BY THE CITY COUNCIL                                |
|     | NAME OF CONTRACTOR  |   |
|     | Note This permit covers work outside of building on   | and Anymork inside                                      |

of building is subject to Massillon Board of Health Regulations.