Nº 5073

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-26-47	
DATE INSPECTED // LU 1	IF SO HOW AND LOCATION FROM
	FIRST MANHOLE DOWN STREAM
HOUSE NO. 2148	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	Boger
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LAT	ERAL TO WALL OF BUILDING SERVED. Foundation not started
	Poundation is started
	-> 10' K
· · · · · · · · · · · · · · · · · · ·	Line curved & Sk. 17 Sh. Curb Line to miss tree 112
	Line curved & SK. T. SN. Curb Line to miss tree
	main Jens
	to miss tree
	To Miss
^	145
when to I	ELLED AT ENGINEER'S OFFICE 12/1/4/
SIGNED INSPECTOR FOR CIT	TIED AI ENGINEERS OF THE
REMARKS:	

N? 5073

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Massillon, Ohio.	11/27 1947
RECEIVED OF 18 18 Clasker	FEE OF \$2 VV
FOR WHICH PERMISSION IS GRANTED) +)+ OHa	shelf
A	_10
TO TAP Santany SEWER, ON THE	north SIDE
of han and MAVE TYPE OF STREET_	vilou
,	
THE PREMISES BEING LOT NO. 6785 , HOUSE N	10. 2148
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY	PASSED BY THE CITY COUNCIL, AND

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND

Juran 15

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.