## Nº 5094

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3 - 10-48	IF SO HOW AND LO				<u> </u>
HOUSE NO					
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH				
WAS LATERAL AT CURB?			ż		
WAS ATTACHED TO MAIN	NAME OF CON	a transfer of the control of the con	ton.	<u>T</u> .	
SHOW BY DIAGRAM RELATION OF LATE		F BUILDING SERV	ED.		
3RD ST. S.E	,		1 6		
	" <b>a</b>		64.5%	t (	
A/				( A	
MARTIN PLESS AND	**************************************			1 64	east :
	e con			17 8 43	1
		September 1995 Annual Control of the	ercuerti. Beresta (vicina), mel esper escribar peregui regioner rec	an mandalan kan kan kan kan kan kan kan kan kan k	To the contract was a page of the contract of
1 on 17				metro a management of the property	U.
SIGNED John Shins		FILED AT ENGINE	ER'S OFFIĈE	3/24/18	
REMARKS:				- the Mark the control of the contro	

## Nº 5094

## PERMIT TO TAP SEWER

	3/18
$24.0 \pm$	FEE OF \$
FOR WHICH PERMISSION IS GRANTED TOUR	Engleman
TO TAP Santary SEWER, ON	THE west SIDE
OF 370 ST. TYPE OF	STREET beloa
THE PREMISES BEING LOT NO. 8173	, House No

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR & USLOW

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.