Nº 5393

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-7-50	IF SO HOW AND LOCATION FROM 59'	12'deef,	
HOUSE NO			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	9. doef	
WAS LATERAL AT CURB?	<i>n</i>		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIANA		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
27TH 5T, N.	Line of the second seco	14	
		17 tex	
(<u>V</u>	49 gideaf	
	7/1	119 6 7 000	
1-1	0 - 2 7	38450	
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	Service Servic	
REMARKS	the state of the s	and the state of t	

Nº 5393

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	2/16 50
A MASSILLON, C	Оню,
RECEIVED OF A. Jana	FEE OF \$2
FOR WHICH PERMISSION IS GRANTED	Bechett
FOR WHICH TERMISSION IS CHARACTED TO	,
TO TAP SUNITARY SEWER, ON THE	last side
274/1 hl	dirt
outside eng 322 d 323	USE NO. 358
THE PREMISES BEING LOT NO	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.