Reform to, Engineer's office Following Data to be answered by inspector

## Nº 6155

## AND SIGNED WHEN RETURNED.

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	77'	3'Dx
HOUSE NO. 631			
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURBY NO	In the Carlotte Community of the communi	est desperator de la companya de la	
WAS ATTACHED TO MAIN Yes	NAME OF CONTRACTOR	2. Willow	7
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SERVED	( A ( A ( A ( A ( A ( A ( A ( A ( A ( A	
	a distribution de la companya de la Companya de la companya de la compa		
	ray (m. 17). 18 maay - Alban Marian Marian, 1884 - 1885 - 1885 - 1885 - 1885 - 1885 - 1885 - 1885 - 1885 - 1885 - 1885 - 18	and the second second	
		3 de	, <u>o</u>
	in to experience Williams of the production of production with the second section. Williams with the second section of the sec		7
		201	1.01
		erosti nee saaali	1000
9. 0		18	27'()
SIGNED WOY ACU	FILED AT ENGINE	ER'S OFFICE	Y
REMARKS:	i estibleció elistojduk il gelitib	rd Serellaw (All Jacque	

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	12/5/53 10
RECEIVED OF Aban + Cunsl	LA FEE OF 5
FOR WHICH PERMISSION IS GRANTED The feet of	there ill
TO TAP Santa SEWER, ON THE	vert
of hele PIM AVE. TYPE OF STREET D	ling
THE PREMISES BEING LOT NO. 770 218, HOUSE NO.	631
Work to be done in accordance with Ordinance No. 2323, buly p.	ASSED BY THE CITY COUNCI

Note This permit covers work outside of building

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Nº 6155

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.