MCOLN Syhook 31/2 DEEP CLEAN OUT 6'FROM WALL
51/2'DEEP NORTH CURB 7/2 Deep ι/٥ 500 UNION COMMERCE BLDG.

Nº 6788 AND SIGNED WHEN RETURNED

DATE INSPECTED	FIRST MANHOLE DOWN STREAM		<u> </u>
HOUSE NO.	•		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	il-	:4
SHOW BY DIAGRAM RELATION OF LATE	· ·		
Barrier and the contract of th	and the second of the second o		2.7
		·	
	and the second of the second o	•	
AND STATE OF A VEHICLE CONTROL OF A VEHICLE CONT	strekko osteka oko eti zisteta kelistak kala olistaria konkoloria zia zia zien. Li distrika konkoloria statut olimoi eko etekzita istoloria eta ziatut.		
ar,		•	
SIGNED	FILED AT ENGINEER'S OFFICE	•	i i i
INSPECTOR FOR CIT			
THE REPORT OF THE PROPERTY OF	landringeld en beljene et mis Dordmenterel	•	

-16

Nº 6788 PERMIT TO TAP SEWER

	MASSILLON, OHIO, May 13
•.	RECEIVED OF HAYAU G. Wilau FEE OF \$ 200
-	FOR WHICH PERMISSION IS GRANTED ARANA A Education
:	TO TAP DALL SEWER ON THE WITH
	OF SAUCH DE AVE. TYPE OF STREET BAUCK
	THE PREMISES BEING LOT NO. 1033 , HOUSE NO LINE BLIN LORO

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR SANTALL D. WINTER

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.