Nº 6949

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-30-55	IF SO HOW AND LOCATION F		
HOUSE NO. 2036			
SIZE OF PIPE USED6	DISTANCE FROM FIRST MANH DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	LINE 9'D FIND RUNS IN I	TO MY
WAS LATERAL AT CURBY YES	<u>ala</u> di salah pelab ihan dinambankan T	e e andre average a transport per estados.	
WAS ATTACHED TO MAIN	. — NAME OF CONTRACTOR_	A V DIANA	
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDIN	G SERVED.	
		70 19	
		, ros amis respensara men	
		The state of the s	
	← 20 →	KUR BYD DAS ROBS (WA) 1	
		VSE 3 &	BENDS"
SIGNED William & While	.		
INSPECTOR FOR	CITY	T ENGINEER'S OFFICE	

12-40

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

그는 그 가장 마루 그는 그는 그는 트립을 회사를 만든 만든 다시다. / 그는 말을 통화
Massillon, Ohio,
RECEIVED OF (1 & Company) FEE OF 5.5
FOR WHICH PERMISSION IS GRANTED POR A MICHAEL BOLL
TO TAPSEWER ON THE
OF TO PIE AVE. ST. TYPE OF STREET
(A, A, A
THE PREMISES BEING LOT NO.
오마 의 기는 말이라는 이 아는 마음을 받아 하는 네트 아는 그리고 가는 이어 마음도했다.
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.