Nº 8223 AND SIGNED WHEN RETURNED

DATE INSPECTED 7-6-20	
DATE INSPECTED	IF SO HOW AND LOCATION FROM TAPPED MT 7 DIE &
HOUSE NO. 941	
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR LEROUSCHUMACKER
SHOW BY DIAGRAM RELATION OF LATE	/ 1 · · · · - · · · · · · · · · · · · · ·
and the second of the second o	70'
n en en la Paris Diagnos de la compresa de la composição de la composição de la composição de la composição de	TOREWALK
·	CORB
	20 0
0. 1	to kind and the second of the
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE
	in The second problems to ethick the second of the second

3 Word

Nº 8223

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	Section 1
,	MASSILLON, OHIO, MUNT
	RECEIVED OF SHAPE CHESTINGS FEE OF \$5.
FOR	WHICH PERMISSION IS GRANTED A PAY ACKNORIA THE
то_т	hanted United
OF_	Wall Ad 71 G. AVE. TYPE OF STREET Hard lad are
THE	PREMISES BEING LOT NO. 6792 HOUSE NO. 941
•	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR SCHURE ACC

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.