

✓
Nº 8271

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 11-19-70

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

REPAIR

HOUSE NO. 1133

SIZE OF PIPE USED 6"




DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN NO

NAME OF CONTRACTOR R. G. MARKS

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

A. Nathan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

Rock between Storm Sewer and Lateral broke down
San Lateral

Repair

Nº 8271

OFFICE OF THE DIRECTOR OF PUBLIC SE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *November 19*

RECEIVED OF *Roeve Marks* FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *Richard Reichel*

TO TAP *Sanitary* SEWER ON THE *South*

OF *Howard Ave. N.E.* AVE. ST. TYPE OF STREET *Chapman St.*

THE PREMISES BEING LOT NO. *8345-PA 8346*, HOUSE NO. *1133*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AN
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Marks*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.