

Nº 8632

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

3-26-73

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

851

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

4"

WAS LATERAL AT CURB?

NO


WAS ATTACHED TO MAIN

YES

NAME OF CONTRACTOR

H. S. NO. 851
HOLDIERBAUM

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

S. Latham

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair
N^o 8632

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *March 26*

RECEIVED OF *Max Lamb* FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED

TO TAP

Repair Sanitary
9th St. N.E.

SEWER ON THE

West

OF

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

5293

HOUSE NO.

851

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Kolderbaum

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**