## Nº 9097

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN NAME OF CONTRACTORSHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
House down	- Plugid at trasport	
SIGNED FILED AT ENGINEER'S OFFICE		
REMARKS		

**№** 19097

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, SEP 2
RECEIVED OF Colored T	Sores FEÉ OF NO 7
· · · · · · · · · · · · · · · · · · ·	1 Massillon, Okio
TOTAP SAIVITHRY SEV	
OF 2010 57 5 42 AVE. ST. TY	PE CF STREET CAUP & SEAL
THE PREMISES BEING LOT NO. 10828	, HOUSE NO. 4774
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	D. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RE

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.