**№** 9393

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	DATE INSPECTED /0 - 10 - 80	IF SO HOW AND LOCATION FROM 34 FIRST MANHOLE DOWN STREAM
	SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
	WAS LATERAL AT CURB? 1	
	WAS ATTACHED TO MAIN	NAME OF CONTRACTOR.
	SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
	The second secon	EASTOF CORNER OF HOUSE
\	34 -> REP	CACED II'OF PIPE AND 300 Bon
part .	SIGNED Inspector for City	ndon filed at engineer's office
	REMARKS	

RETWEEN
LIONARD

REPAIR

 $N^{\circ}$  9393

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO	, Oct. 8
RECEIVED OF Mula	Culcum	FEE OF \$ 25.
FOR WHICH PERMISSION IS GRANTED	Winding.	
TO TAP Sanctary	SEWER ON THE	
OF 19# 10 71.W.		The state of the s
THE PREMISES BEING LOT NO	and the control of th	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RI

NAME OF CONTRACTOR Halduckaum

OF THE DEPARTMENT OF PUBLIC SERVICE.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.