FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12.20 82 HOUSE NO. 43	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	N:
WAS LATERAL AT CURB?	NAME OF CONTRACTOR	HOLDERBAUM
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WAI	NAME OF CONTRACTOR L OF BUILDING SERVED,	

REPAIR

17' DO CLEAN OUT S' DEEP

SIGNED William Passage FILED AT ENGINEER'S OFFICE	
---	--

REMARKS

Repair

№ 9509

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON	, oHIO,	N.c.	20
RECEIVED OF Holdiebaum			FEE OF \$ 2 2
FOR WHICH PERMISSION IS GRANTED / Middle House			
Repair Sewer on THE		Mart	
OFAVE. ST. TYPE OF STREE	≣τ <i>_</i>	May L. T.	72
THE PREMISES BEING LOT NO. 3744	_, HOUSE NO.	<u> </u>	3
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR / Statistaum	· (******	The same and the same of the s

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.