

Nº 9666

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED FEBRUARY 19, 1985

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 4106

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N ←



SIGNED Harold Sasaki
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS Put New Clean-out in BACK OF HOUSE Flows To Andrew N.E.

1694
No

9666

REPAIR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

FEE 15

RECEIVED OF

HOLDERBAUM

FEE OF \$

25

FOR WHICH PERMISSION IS GRANTED

REPAIR

TO TAP

SEWERS

SEWER ON THE

West

OF

SENECA

AVE.

ST. TYPE OF STREET

BLACKTOP

THE PREMISES BEING LOT NO.

1951 1952

HOUSE NO.

405 SENECA

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

HOLDERBAUM

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**