N^{o} 970

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2 20 - 86 HOUSE NO. 1370	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 455	NAME OF CONTRACTOR Schalmo BIDERS.
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	
	GREASS E. THI
	TRAPS 5. 88' \$
SIGNED William Pappers	FILED AT ENGINEER'S OFFICE
/Inspector for City	t de la companya de

REMARKS Did Not SEE GREASE TRAPS SET IN, OF CONNECTED Together.

7/14/106 № 9703

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON,	оню, ДС	4
RECEIVED OF 1 111 1 7 7 11	ul, Frals	1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 / 1 /	FEE OF \$
FOR WHICH PERMISSION IS GRANTED			
TO TAP	SEWER ON THE.	40-61	
OF MAN LOW ANGSIL			
THE PREMISES BEING LOT NO. 41	14/23	, HOUSE NO	1370
WORK TO BE DONE IN ACCORDANCE WITH ORDIN OF THE DEPARTMENT OF PUBLIC SERVICE.	NANCE NO. 19.1971	DULY PASSED BY T	
NAME OF CONTRACTOR	o Vilda	<u> </u>	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.