## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

11	
L	
bearing the same of the same o	

Date Inspected If so how and location from 9800 first manhole down stream House No. Distance from first manhole down stream to ditch at Size of pipe used. curb line and depth ... Was lateral at curb?\_\_/ Name of Contractor. Was attached to main / Show by diagram relation of lateral to wall of building served.

Filed at Engineer's Office Inspector for City Remarks

Signed

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## **Nº** 1918

## PERMIT TO TAP SEWER

where $x_{ij}$ is a sum of $x_{ij}$ and $x_{ij}$	Marka Britania (Kristoper e medelja metok). Geografija	Massillan O	C 1	4 100
	a sa an magani saga sa A wan fan Domesto Shaansis San safa afan wan san sa	massiion, O.,		19
Received of	h. C. K.	Anh	fee of \$	2 Commence
for which many in the	granted Je			The Control of the Co
for which permission is	granted		madde.	
to tap	sew sew NOME WAY N.W	er, on the	H Int	side
of MLin	ICOLY WAX	A	9800	) <b>~</b> © /
OI		St. St.	es being Lot. No.	<u> </u>
House No. 1406	Work to be done in	accordance with	Ordinance No. 232	3, duly passed
	d Rules of the Departmen			
Lettino Procession and	rigard of frage			age of \$35