FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 2205

AND SIGNED WHEN RETURNED 4-18

Date Inspected June 14 th	If so how and location from first manhole down stream
House No. New 237	Distance from first manhole
Size of pipe used & in	down stream to ditch at curb line and depth
Was lateral at curb?	
Was attached to main	Name of Contractor fee Bunker
Show by diagram relation of lateral to	wall of building served. House
	150 ft- pipe
	and the second s
	Korman Bold -> West-
Signed A 7 Bayol Inspector for C	Filed at Engineer's Office JUN 1 4 1926
Remarks Lataral connec	ted to man hole 58 ft from stait line on

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2205

PERMIT TO TAP SEWER

Massillon, O.,
Received of less Brunke fee of \$ 2 00
for which permission is granted har Hellense
to tap sanitay sewer, on the south sid
of St. Ave., the premises being Lot. No. 4009
House No
by the City Council, and Rules of the Department of Public Service.