FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected May 19 742	If so how and location from first manhole down stream
House No. New 742 Size of pipe used & M	Distance from first manhole down stream to ditch at curb line and depth.
Was lateral at curb?	Name of Contractor Bensher 4 Deshon
tina di para di para di mandra di para di mandra di mandra di para di para di mandra di mandra di mandra di ma Mandra di mandra di m	to wall of building served; אמנים או

PROBLEM SERVICES SERVICES FOR THE PROPERTY OF

e vila Umanasce de. III., dely pessa by ibsains Comell, con Iclas a

Signed A of Boyd Rotch are West MAY 21.

Reparks: Saleral Connected to lateral at every 64 ft from St.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2956

PERMIT TO TAP SEWER

Received of digst buy out these factors and distributed as the second of the second digst buy out these factors and the second digst buy out these factors are the second digst buy out these factors and the second digst buy out the second didst bu	0.0
	fee of \$
for which permission is granted. I the Chracker	= SZJ
to tap. Auntitudy sewer, on the control of Rotal Was an internal to control of several and the control of Street.	enagossi ibridgiosik Aug
3986 St., the premises being Lot No. 2256 , House No. 742	
Work to be done in accordance with Ordinance No. 2323, duly passed by the City the Department of Public Service.	Council, and Rul

NOTE. This permit covers work outside of building only. Any work inside walls of bui is subject to Massillon Board of Health Regulations.