FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Aug 27 Double House No New	I so how and location from first manhole down stream
	Distance from first manhole down stream to ditch at
Size of pipe used 6 m	curb line and depth
Was lateral at curb?	
	Name of Contractor fless Bunker
Was attached to main	724
Show by diagram relation of latera	l to wall of building served.
	<u>s/1</u> / °
	66 ft Och

Mo 3030

Signed 4 - 9- Band Filed at Engineer's Office AUG 2 8 1928

Remarks: Saleral Connected to lateral at curb (ff from strait

office of the director of public service N_{\star}^{c} 3039 PERMIT TO TAP SEWÉR

	i noisecol bus well or I		baloggi aja ivilū
	orie wwele elodinem fesif.	Massillon, O.,	1
	laser derif aydr soanteid.		
	deceb ens enil deceb		fee of \$
for which permission is gr	,我就被我们一笑,"我说," 是 一点,"我们的,我们的我们的"。 (2) "你们的","我们的","你们的","我们的"。	and the first of t	
	i lesainoù lesain	r, on the	i benenie wy
to tap	<u>-ryy i ya ya mana a sawa</u>	r, on the said is noticed to	erelled Wale
	11/2/2	Ave., Type of Street	9.4
		St.,	
the premises being Lot No) <i>U.</i> /_6	, House No	
Work to be done in accor-	dance with Ordinance No	. 2323, duly passed by the	City Council, and H
and the second section of the second section is a second section of the second section of the second section of	ganagering and a single finite production of the read read and the second section of the second section of the		
the Department of Public	: Service.		
	The second secon		
Name of Contractor/			

NOTE. This permit covers work outside of building only. Any work inside walls of bu

is subject to Massillon Board of Health Regulations.