FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Oc1-30	I so how and location from first manhole down stream	
House No. <i>440</i>	Distance from first manhole	
Size of pipe used 6	down stream to ditch at to device and depth	
Was lateral at curb? Med	tantang di notang at notang di	
Was attached to main	Name of Contractor Dan John	
Show by diagram relation of latera	to wall of building served	
Type of Street	2018년 1일 - 1일 시간 원인한 화교로 문화적인화한 경험 에 설명되었습니다. 그는 1일 	
en e	Part-By	
duly gaveled by the Olly Council cultificiles (ESET OF ENHERING SHEW SOLE / 1998 HI SHUD SOLETHIN	
	Man Lewer North <	
1 OL P	and the state of the second control of the control of the second of the	neto i
Signed The Doy	Filed at Engineer's Office	
inspecto	26 ff SI-N: W Filed at Engineer's Office r for City meded to lateral at cital 4ff fro	1/2
Remarks: Saleral Con	meded to fallial at ciero 4 ft fro	m xxx
	line on	House

N9 3105

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE Nº 3105 PERMIT TO TAP SEWER

Massillon, O., for which permission is granted Ave., Type of Street. the premises being Lot No. 8028, House No. 440 Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service.

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.