FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED 3659

Date Inspected 109-23 House No. 359 Size of pipe used 2011	I so how and location from first manhole down stream Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor Bes Brunker
Show by diagram relation of lateral	to wall of building served. //our // // // // // // // // // // // // //
House No. 2002 William Idea (Street and American)	
1 OLD .	Main Bers North C NOV 3

Remarks: Sateral Councoled to Sostenal ad County 129 /1- Loren Mar Hale

office of the director of public service N_{\cdot}^{o} 3659 PERMIT TO TAP SEWÉR

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.