

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM**

196' Reat of Bldg. 18" mal

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No.

NAME OF CONTRACTOR

P. E. Bickel

WAS ATTACHED TO MAIN Hob Saddle

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED

Lateral 14' Deep at 18" main line

Laternal 10' Deep at Mt.

Laternal 176' MH. to connection

SIGNED

Carlisle M. Olson

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

630-41

0/40

REMARKS:

Slip Seal joints

M. Built by contractor

Entered in ledger July 1, 1941
E.E.T.
\$325.00
Pete

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
No. 4238
PERMIT TO TAP SEWER

Steel
near

Steel

MASSILLON, OHIO, 6/9 1941
RECEIVED OF P. E. Bickel FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Republic Steel
TO TAP Line SEWER ON THE W
OF 410 Charles Rd S.W. AVE., TYPE OF STREET Rich
ST.,
THE PREMISES BEING LOT No. 2294 HOUSE No. 410
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR P. E. Bickel

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.