

"NEW lateral"

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o. 4326

DATE INSPECTED 5-21-42

IF SO HOW AND LOCATION FROM
FIRST MANHOLE up STREAM

109' out in street

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Hub Saddle

TYSON Roller
Beating Bldg.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lateral - 11' Deep at main

Lateral - 3.5' Deep at curb line

Lateral - 2' Deep at Bldg.

Lateral - 21' Long Bldg. to main

No curb "curb line"

← SEWER

Pennoek Ave. S.W.

SIGNED

Julius Johnson
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

W. G. W.


May 22 1942

REMARKS:

+ mark on side of Bldg. "clay soil"

(over)

A mach 10 ft in with Hub saddle
(2) Two joints straight up, then a 90 Bend
Bend is 6' Deep



OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 4326
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5712 1915
RECEIVED OF P. E. B. Co. FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Lynn's Roller Bearing
TO TAP Sanitary SEWER ON THE North
OF Pennsylvania Ave. TYPE OF STREET and
St. oil
THE PREMISES BEING LOT No. not lot number HOUSE No. not
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR P. E. B. Co.

Note. This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.