## $N_{\cdot}^{0}$ 5271

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-5-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	·
WAS LATERAL AT CURB? 12.5	A company	
WAS ATTACHED TO MAIN 725	NAME OF CONTRACTOR	<b>—</b> ₹
SHOW BY DIAGRAM RELATION OF LAT		
OXFORD. A	rei N.E.	
	3	`c/s
	7. dea/1 /26	and the second section of the section of the second section of the section of the second section of the
SIGNED John English INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 5-17-49	egan seriiri indinen dilegal lind artikani maddy
REMARKS:		

## Nº 5271

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	5//	
	MASSILLON, OHIO,	194/
RECEIVED OF	FEE OF	200
OR WHICH PERMISSION IS GRANTED	ton Ordean	
1.	er, on the	SIDE
101.0 0 SIE	PE OF STREET COLOR	
HE PREMISES BEING LOT NO. 8500	, House No	
VORK TO BE DONE IN ACCORDANCE WITH ORDINAN	CE NO. 2323. DULY PASSED BY THE CITY	COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.		
IAME OF CONTRACTOR		

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.