## 5351

 $N_0$ 

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

14
446

DATE INSPECTED 9-/6-79	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	·
HOUSE NO. 2/30		•
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8'dech
WAS LATERAL AT CURB?	h. I	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DULACA	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	-6deep
Duan ≥	eAve, S	2 deep 112
	- American American	
SIGNED John Jan	FILED AT ENGINEER'S OFFICE	E 9-16-49
INSI ECTOR FOR CITY		
REMARKS:		

## Nº 5351

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO, 9/5
RECEIVED OF It line	Mbaugh FEE OF \$2
FOR WHICH PERMISSION IS GRANTED	
TO TAP Sandany	SEWER, ON THE
$\sim$ $M_{\rm A}$	ST., TYPE OF STREET ST.
THE PREMISES BEING LOT NO. 6039	, House No2/30
WORK TO BE DONE IN ACCORDANCE WITH C	ORDINANCE No. 2323. DULY PASSED BY THE CITY COUNCIL AND

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.