Kelay Job. Mark to by

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 9-2/53 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	54 M.H. to "Y"
HOUSE NO. 830	· · · · · · · · · · · · · · · · · · ·
SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	r transmission Transmission Transmission
WAS LATERAL AT CURB?	and Market general Market Market (1997) - 1997 - 1
WAS ATTACHED TO MAIN OF SINCE NAME OF CONTRACTOR	Remley.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERV	ED.
Relaid from main to side walk line.	Maria
Kelala 180 187 Mam	, // -
to side walk Ime.	And the state of the contract
ineraktekarati kigi da birkara elektri ili dibik ili dili ili kultu tutuk kiki kirinta birgikat (Turkarati kirinta kirinta kirinta biraktara birgi katalan kirinta kirinta kirinta kirinta biraktara birgi kat	152 Deep E. Curb In
	-7'Decp 1710100
	D> I am
07/1	54'
SIGNED W. J. STANDER SILED AT ENGL	NEER'S OFFICE
NSPECTOR FOR CITY	Rind And Char
REMARKS: Repaired & relaid.	reason and subsequently

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE 6236 PERMIT TO TAP SEWER

ing and the second seco	ranger (n. 1885). De la francisco de la franci	7/20
R P	Massillon, Ohio,	15
RECEIVED OF	nur And Boy	FEE OF \$_5X
TO TAP	SEWER, ON THE	E.
or Jensen n.E.	AVE., TYPE OF STREET	
THE PREMISES BEING LOT NO. $96/$	g , House No. 4	830
WORK TO BE DONE IN ACCORDANCE WITH	ORDINANCE No. 2323, DULY PA	SSED BY THE CITY COUNCI

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.