Nº 6999

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

2 11 1-		2ND MY WEST of	2 ARVEY
DATE INSPECTED 3-11-59	IF SO HOW AND LOCATION FROM / TELEFITY TO THE PROPERTY OF T	y" 70 WEST	7'0e
HOUSE NO. 2/58			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	en e	
WAS LATERAL AT CURBI NO	and the Albanda of the Astronomy of the second	than the constitue of the	
WAS ATTACHED TO MAIN YES	- NAME OF CONTRACTOR	loe Y Inc	
SHOW BY DIAGRAM RELATION OF LAT	TERAL TO WALL OF BUILDING SERV	VED.	
		17	
		70 76'	
		21'	10
SIGNED Roy Vatha	FILED AT ENGI	NEER'S OFFICE	
Inspector for C		y in the Horizontal Control	
REMARKS			the second second

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

YNY 6999 PEKMII IU IAP SEWEK
이 문의 공료 이 아이 되지만 되었습니다. 얼굴 🖊 그림 안 달길
Massillon, Ohio, 19
RECEIVED OF THE FEE OF S 2
FOR WHICH PERMISSION IS GRANTED M4 (A Bld.
TO TAP 64 A SEWER ON THE
OF_ PA 10,) 77 LAVE. TYPE OF STREET ALTH
THE PREMISES BEING LOT NO. 11908 , HOUSE NO. 21.58
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL,
Rules of the Department of Public Service.
NAME OF CONTRACTOR AND A AND
Note This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.