Nº 7402

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	HOW AND LOCATION FROM T MANHOLE DOWN STREAM
HOUSE NO. 1136	MANHOLE DOWN SIREAM
SIZE OF PIPE USED CORE	ANCE FROM FIRST MANHOLE N STREAM TO DITCH AT 81 South of 1 8 Deep
WAS LATERAL AT CURB? YCS	
WAS ATTACHED TO MAINNAM	IEOFCONTRACTOR DROPELS
SHOW BY DIAGRAM RELATION OF LATERAL T	O WALL OF BUILDING SERVED.
	-1
	The state of the s
	$\frac{1}{\sqrt{1}} \left(\frac{2}{\sqrt{1}} \right)^{\frac{1}{2}} \int_{0}^{2\pi} \left(\frac{2}{\sqrt{1}} \right)^{\frac$
SIGNED ROJ Latham	FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CITY	error of the filter of perfection in the
REMARKS	•

17-14 Nº 7402 8-21-61

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Leale Ragars & RAMABSILLON, O	ню, Марар 30 19
RECEIVED OF MOSILIANA THORAGSILLON, OF	FEE OF \$ 5 =
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER ON THE	east
of 35 Hc 714) AVE. ST. TYPE OF STREET_	1/4/21
THE PREMISES BEING LOT NO. 7089	OUSE NO. 436

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR AUTO KARCES T KOUS

Note This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.