

NO. 7959

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 7-
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-28-67

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

REPAIRED IN ST.

HOUSE NO. 1315

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

R MARK:

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N

GAS L.

STORM S.

12' 2"

3'

BROKEN @
STORM SIEW

SIGNED

[Signature]

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS

CUT OFF WHEN STORM SEWER CONSTRUCTED

OFFICE OF THE DIRECTOR OF PUBLIC SEWER SERVICE
PERMIT TO TAP SEWER

Nº 7959

Relay

MASSILLON, OHIO

February 28

RECEIVED OF

Donald L. Brown

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

Recess Works

TO TAP

Sanitary

SEWER ON THE

South

OF

Donald Ave. S.W.

AVE.

ST. TYPE OF STREET

City & Local

THE PREMISES BEING LOT NO.

8873

HOUSE NO.

1315

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Marks

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**