

1811

✓
Nº 8049

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-31-68

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 11289

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

159' W. OF DEAD END H/W


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR _____

G. MALAVITE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED _____

[Signature]
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

N^o 8049

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, MAY 21 1911

RECEIVED OF COST MALAVITE FEE OF \$ 5.00

FOR WHICH PERMISSION IS GRANTED COST MALAVITE (J. HUNTER, OWNER)

TO TAP SAN. SEWER ON THE NORTH

OF GORDON PL. NW. AVE. TYPE OF STREET CHANCE

THE PREMISES BEING LOT NO. 11232 -1 HOUSE NO. 11237 2970

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR MALAVITE

Note: This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.