## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR **№** 8597

Inspector for City

AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 4 CIP.	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR M. HOLDEY BAU
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	15'
	N C
·	Vican 200
4	
	CI.P. Z'DALD LAT.
Į.	,

REMARKS REPAIRED SOUND SEPTIC TANK ABANDONE

\_\_\_\_\_ FILED AT ENGINEER'S OFFICE\_\_\_\_\_

repair

**Nº** 8597

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

1- 20

	MASSILLON, OHIO, 1 Commune 17,		
RECEIVED OF MALALUAGE	FEE OF \$		
FOR WHICH PERMISSION IS GRANTED LUCE	<u>Patha</u>		
TO TAP	<i>f</i>		
OF AVE.	TYPE OF STREET 1990		
	, HOUSE NO		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	un		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.