

Nº 10123

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 8-27-91

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 39'6" downstream Manhole

HOUSE NO. 405

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Humbert Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*10'7" from south end
of building
6 1/2' deep*

Andrews



N -

*5' piece cut from building
22 1/2° Elbow
2' piece
4" ferreo*

39'6" Downstream MH

Parkview

SIGNED *David Miller*
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS *Repair - used plastic pipe*

repair

Nº 10123

OFFICE OF THE DIRECTOR OF PUBLIC SEI

PERMIT TO TAP SEWER

MASSILLON, OHIO.

Aug 26

RECEIVED OF

Humbert Exc

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

same

TO TAP

San

SEWER ON THE

North

OF

Parkview NE

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

1299

HOUSE NO.

405

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Humbert Exc Dave Schwemmer

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.