Nº 10249

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED \2/16/92	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN 405	NAME OF CONTRACTOR HOLDERBAUM (LEWIS)	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	SAAW	
•	हिं के प्रमुख । जिस्से । इंट्रेंटी	
SIGNED LUQ Q M Cuo	FILED AT ENGINEER'S OFFICE	
Inspector for City		
DEMARKS		

Nº 10249

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,
RECEIVED OF OUND	FEE OF \$
OR WHICH PERMISSION IS GRANTED	
O TAPSANITAS	EWER ON THE SOUTH
AVE. 1	TYPE OF STREET
THE PREMISES BEING LOT NO	, HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE OF THE DEPARTMENT OF PUBLIC SERVICE.	NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR	elegeber

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.