$N^{\underline{0}}$ 10595 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED		IF SO HOW AND LOCAT FIRST MANHOLE DOW			
HOUSE NO		DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?		¥			
WAS ATTACHED TO MAIN SHOW BY DIAGRAM RELATION					
	INSPECTION				
				markan sanaran	
SIGNED	Inspector for City		_ FILED AT I	engineer's office	
REMARKS					

Nº 10595

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MAS	SSILLON, OHIO, MAY 13
RECEIVED OF Slyn and	revike FEE OF 5.5
FOR WHICH PERMISSION IS GRANTED.	<u> </u>
TO TAP A SEWER	ON THE TUNTER
OF MALLY 9161 AVE. TYPE O	FSTREET ARRIVATION
THE PREMISES BEING LOT NO. 13959	f
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19	3-1971 DULY PASSED BY THE CITY COUNCIL, AND
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19 OF THE DEPARTMENT OF PUBLIC SERVICE. NAME OF CONTRACTOR THE ACCORDANCE WITH ORDINANCE NO. 19	mb-

_

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.