Nº 11074

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-3/-00 HOUSE NO. 1400	IF SO, HOW AND LOCATION FROM 69	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
WAS LATERAL AT CURB?	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN _ 1/5 5	NAME OF CONTRACTOR Strendles The	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	7' 10' 2'	
SIGNED Bill Park	FILED AT ENGINEER'S OFFICE	
REMARKS		

 $N^{0} = 11074$

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MĄSSILLON, OHIO,	May 3000_
RECEIVED OFMala	vite	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Molavite Excount	ing
REPAIR TO TAP SOUND !		9
ситогг — <u>С.Б.Sc.Л. Д.Р.</u>	AVE. ST. TYPE OF STREET	asphatt
THE PREMISES BEING LOT NO.	, HOUSE NO	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE	NO. 19.1971 DULY PASSED BY THE	CITY COUNCIL, AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.	,	,
NAME OF CONTRACTOR MAIAU	:1e	- North-Citing

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.