Nº 11267

REMARKS

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 242	IF SO, HOW AND LOCATION FROM COS C THIS MA
SIZE OF PIPE USED WAS LATERAL AT CURB?	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DESCO
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BL	6x4 120- 66 11/2 120 11/2 11/2 11/2 11/2 11/2 11/2
SIGNED But Value Anspector for City	FILED AT ENGINEER'S OFFICE

Nº 11267

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OF	ню,	<u>/8/61_,20_</u>
RECEIVED OF	- Annual Designation of the Control	FEI	EOF\$
FOR WHICH PERMISSION IS GRANTED	Vasco Asp	shalf-	
REPAIR TO TAP CULTURE	•	North	
OF Lacule when the			
THE PREMISES BEING LOT NO.			
WORK TO BE DONE IN ACCORDANCE WITH O	ORDINANCE NO. 19.1971 DULY PASSE	ED BY THE CITY COUNCIL,	AND RULES OF THE
DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	1a50	·	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.