Nº 11376

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-17-0 / HOUSE NO. 2185	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE		
WAS LATERAL AT CURB?	DOWN STREAM TO DITCH AT. CURB LINE AND DEPTH		
WAS ATTACHED TO MAIN 35	NAME OF CONTRACTOR Molumits Edge		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
	14' 8'PFF 22° 11'DEEP		
SIGNED Bull Control Inspector for City	FILED AT ENGINEER'S OFFICE		
PEMARKS			

Nº 11376

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

$\sim \Lambda \Lambda \sim 14$	MASSILLON, OHIO,	/0//,20
RECEIVED OF Waldwite		FEE OF \$5
FOR WHICH PERMISSION IS GRANTED		7.
	R ON THE	ruth
OF AALD CI ENTYPE	OF STREET	undert
THE PREMISES BEING LOT NO	, HOUSE NO	2185
/	OZ4 DINV BARRED BY THE OIT	V COUNCIL AND DIKES OF THE
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19,1	9/1 DULY PASSED BY THE CIT	T COUNCIL, AND HULES OF THE
DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR Muliute		_
•		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.