11420

Nº

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO.	. DISTANCE FROM FIRST MANHOLE			
SIZE OF PIPE USED	··· PITOLIAT			
WAS LATERAL AT CURB?	-			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
See Permit	1 # 1/603			
	FILED AT ENGINEER'S OFFICE			
Inspector for City				
REMARKS				

Nº 11420

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON	, OHIO,	1.2.20	
RECEIVED OF/	Donate of the	with the state of	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED)			
REPAIR TO TAP	SEWER ON THE		Irana.	
OF Williams	AVE. ST. TYPE OF STREET.		1	
THE PREMISES BEING LOT NO. $\underline{\phantom{aaaaaaaaaaaaaaaaaaaaaaaaaaaaaaaaa$	16059	_, HOUSE NO	1 2375	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.				
NAME OF CONTRACTOR	Eldina & Home	De de la companya della companya del	_	

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.