## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	5/3/02	IF SO, HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 49. From upstream M/H						
HOUSE NO	3161							
SIZE OF PIPE USED	6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT						
WAS LATERAL AT CURB?	yes	CURB LINE AND DEPTH						
WAS ATTACHED TO MAIN	yes	NAME OF CONTRACTOR Tissot						
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.								
Not to scole		3161 Lincoln Way # Grease Trap  2.55  32'-22°  22:-3'  49'						
SIGNEDInspector for City		FILED AT ENGINEER'S OFFICE						
REMARKS								

## Nº 11493

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,					
RECEIVED OF	Tisset			FEE OF \$ .	<i>F 10</i> ≠	
FOR WHICH PERMISSION IS GRANTED	)					
REPAIR TO TAP	SEWE	R ON THE	S	noth.		
OF	AVE.	OF STREET	A.	A.H		
THE PREMISES BEING LOT NO	16268	, H	HOUSE NO	1 : 316/		
WORK TO BE DONE IN ACCORDANCE DEPARTMENT OF PUBLIC SERVICE.	WITH ORDINANCE NO. 19.	1971 DULY PASSE	ED BY THE CITY	COUNCIL, AND RUL	ES OF THE	
NAME OF CONTRACTOR	1 3 2 0			•		

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health regulations.