

## CITY OF MASSILLON, OHIO

151 LINCOLN WAY EAST
MUNICIPAL GOVERNMENT ANNEX
CITY ADMINISTRATION BUILDING
MASSILLON, OHIO 44646
PHONE 330-830-1722 FAX 330-830-1786

PERMIT DATE:

02/13/2006

PERMIT NO.

3617

PERMIT TO TAP SANITARY SEWER

'his permit is issued subjec tart of work (330) 830-1722	ct to the latest Codified Ordinand . All permits issued under this or	es of the City of Ma rdinance are void af	ssillon, OH. The C ter 120 days from	City Engli	neer to be notified 24 h issuance.	ours in advance of
RECEIVED OF:		PERMIT TYPE:	<b>☑</b> NEW	REP		
CONTRACTOR INFORMATION		SI	SITE INFORMATION			
CONTRACTOR:	BUILDERS EXCAVATI	NG OV	VNER'S NAN	ЛЕ:	MASSILLON HO	OMES LLC
CONTACT:		sт	REET NUME	BER:	1421	
ADDRESS:	The second secon	ST	REET NAME	<u>:</u>	WOODLAND A	V SE
CITY:	Control Contro	СП	TY LOT NUM	BER	17035	
STATE:		PU	RPOSE OF	CUT:	SANITARY	
ZIP:		ZO	NING CLAS	S:		The second secon
PHONE:	(440) 717-6700	ST	REET SIDE:		SOUTH	
FAX:		PH	ONE OTHER	₹:	(216) 475-8900	
SURETY:	3	NOT walk	E: This permit cov s of the building is:	ers work subject to	outside of the building O the Massillon Board of I	NLY. Any work inside
SANITARY SEW	ER CONNECTION:	ı	SKETCH:		WING #:	
USAGE: 👝 RESIDE	NTIAL O COMMERCIAL O IN			1	4 1 Photogramma (1999)	3617
DATE INSPECTED	2/14/06			142	21 Woodland Ave SE	
located on the	outh side of					
Wood land A	VE SE bet	tween			5'dp	
14th 5+ 51	E and	d	Ν		-23'	
the second section of the contract of the cont	5 E		∜ `		_45°	
Direction from dov	vnstream Manhole: 🗍	East			8'dp T	
Distance from dov	vnstream Manhole: 🗍	8			-21'	
Connection Lengtl	h: 23 0.00 (FE	ET)				curb
Connection Depth	<u> </u>	ET)	<del></del>		O_F,8-I	
Size of Sewer Pipe	61	(INCHES)				
Pipe Material:	Pv	C				
NSPECTORS NAM	آE: J	# King	SANITARY	SEWE	R PERMIT FEE:	\$100.00
COMMENTS:		<u> </u>				The second of the second secon
				T	TOTAL COST:	\$100.00
TWO WORKING DAYS BEFORE YOU DIG			AUTHORIZED E	BY: DIRE	CTOR OF PUBLIC SAF	ETY AND SERVICE
Ohio Utilities Protection Service Call 1-800-362-2764 Toll Free			ISSUED BY		INDA MIKUTEL	THE SERVICE
Non-Membe	rs must be called directly.	744		1		